




Load / 100 sq. mm (N)


J03





Load / 100 sq. mm (N)


J06





Load / 100 sq. mm (N)


J15





Load / 100 sq. mm (N)


J16





Load / 100 sq. mm (N)


J17





Load / 100 sq. mm (N)


J33





Load / 100 sq. mm (N)


J34





Load / 100 sq. mm (N)

J04








Load / 100 sq. mm (N)


J07





Load / 100 sq. mm (N)


J09





Load / 100 sq. mm (N)


J10





Load / 100 sq. mm (N)


J11





Load / 100 sq. mm (N)


J12





Load / 100 sq. mm (N)


J13





Load / 100 sq. mm (N)


J36





Load / 100 sq. mm (N)

J38








Load / 100 sq. mm (N)


J41





Load / 100 sq. mm (N)


J42





Load / 100 sq. mm (N)


J45





Load / 100 sq. mm (N)


J05





Load / 100 sq. mm (N)


J08





Load / 100 sq. mm (N)


J24





Load / 100 sq. mm (N)

J26





Load / 100 sq. mm (N)

J31

