




Machine Extension (mm)


J01





Machine Extension (mm)


J02





Machine Extension (mm)


J03





Machine Extension (mm)


J04





Machine Extension (mm)


J05






Machine Extension (mm)

J10






Machine Extension (mm)





Machine Extension (mm)

J12








Machine Extension (mm)

J13





Machine Extension (mm)

J14

Greatest Slope Point #1

L


L1

324,40  
324,30  
324,20  
324,10  
324,00  
323,90  
323,80  
323,70  
323,60  
323,50

5

10


Time (Minutes)





Machine Extension (mm)


J15





Machine Extension (mm)


J16





Machine Extension (mm)


J17





Machine Extension (mm)


J18





Machine Extension (mm)


J19





Machine Extension (mm)


J20








Machine Extension (mm)





Machine Extension (mm)


J06





Machine Extension (mm)


J07





Machine Extension (mm)

J08





Machine Extension (mm)

J09

