




Machine Extension (mm)


P01





Machine Extension (mm)


P02





Machine Extension (mm)


P03





Machine Extension (mm)


P04





Machine Extension (mm)


P05






Machine Extension (mm)

P06






Machine Extension (mm)





Machine Extension (mm)


P09






Machine Extension (mm)

P10






Machine Extension (mm)





Machine Extension (mm)


P12





Machine Extension (mm)


P13





Machine Extension (mm)

P14





Machine Extension (mm)

P15

Greatest Slope Point #1

L


L1

323,30
323,20
323,10
323,00
322,90
322,80
322,70
322,60
322,50
322,40

5

10


Time (Minutes)





Machine Extension (mm)


P16





Machine Extension (mm)


P17





Machine Extension (mm)


P18





Machine Extension (mm)


P19





Machine Extension (mm)


P20





Machine Extension (mm)


P21





Machine Extension (mm)

P22





Machine Extension (mm)

P23

