




Machine Extension (mm)


U01





Machine Extension (mm)


U02





Machine Extension (mm)


U03





Machine Extension (mm)


U04





Machine Extension (mm)


U13





Machine Extension (mm)


U14





Machine Extension (mm)

U05





Machine Extension (mm)


U06

323,40
323,30
323,20
323,10
323,00
322,90
322,80
322,70
322,60
322,50

Time (Minutes)

5

10




L1

L




Machine Extension (mm)





Machine Extension (mm)


U08





Machine Extension (mm)


U35





Machine Extension (mm)


U36





Machine Extension (mm)

U37





Machine Extension (mm)

U38

322,90
322,80
322,70
322,60
322,50
322,40
322,30
322,20
322,10
322,00


5

10

Time (Minutes)

L1


L





Machine Extension (mm)

U09





Machine Extension (mm)

U10

323,00
322,90
322,80
322,70
322,60
322,50
322,40
322,30
322,20
322,10


5

10

Time (Minutes)

L1

L





Machine Extension (mm)

U11

323,00
322,90
322,80
322,70
322,60
322,50
322,40
322,30
322,20
322,10


Time (Minutes)

5

10

L1


L





Machine Extension (mm)


U12





Machine Extension (mm)


U17





Machine Extension (mm)


U18





Machine Extension (mm)


U19





Machine Extension (mm)


U20





Machine Extension (mm)


U15





Machine Extension (mm)


U16





Machine Extension (mm)


U39






Machine Extension (mm)

U40





Machine Extension (mm)





Machine Extension (mm)

U42

